



United States Department of the Interior

GEOLOGICAL SURVEY

WATER RESOURCES DIVISION 26 P.O. BOX 50166 Honolulu, Hawaii 96850

January 28, 1988

Mr. Manabu Tagomori Manager-Chief Engineer Department of Land and Natural Resources Division of Water and Land Development P.O. Box 373 Honolulu, Hawaii 96809

Dear Mr. Tagomori:

Enclosed are the Analytical results for the water sample collected from Kualapuu Mauka Well, 4-0801-03, Island of Molokai. The data will be stored in our computers in Reston, Virginia. Please call us if you have any questions.

Sincerely,

Enclosure

DISTRICT CODE 15

UNITED STATES DEPARTMENT OF INTERIOR - GEOLOGICAL SURVEY PROCESS DATE 1-27-88

210857157011701 - 4-0801-03 KUALAPUU

WATER QUALITY DATA, WATER YEAR OCTOBER 1986 TO SEPTEMBER 1987

DATE	STATION	NUMBER	DATE	TIME	NITRO- GEN, NO2+NO3 DIS- SOLVED (MG/L AS N) (00631)	HARD- NESS (MG/L AS CACO3) (00900)	CALCIUM DIS- SOLVED (MG/L AS CA) (00915)	MAGNE- SIUM, DIS- SOLVED (MG/L AS MG) (00925)	SODIUM, DIS- SOLVED (MG/L AS NA) (00930)	SODIUM AD- SORP- TION RATIO (00931)	POTAS- SIUM, DIS- SOLVED (MG/L AS K) (00935)	CHLO- RIDE, DIS- SCLVED (MG/L AS CL)
SEP 26	2108571	.57011701	870926	0800	0.28	69	9.6	11	33	2	3.0	64
DATE	SULFATE DIS- SOLVED (MG/L AS SO4) (00945)	FLUO- RIDE, DIS- SOLVED (MG/L AS F) (00950)	SILICA, DIS- SOLVED (MG/L AS SIO2) (00955)	ARSENIC TOTAL (UG/L AS AS) (01002)	BARIUM, TOTAL RECOV- ERABLE (UG/L AS BA) (01007)	BERYL- LIUM, TOTAL RECOV- ERABLE (UG/L AS BE) (01012)	CADMIUM TOTAL RECOV- ERABLE (UG/L AS CD) (01027)	CHRO-MIUM, TOTAL RECOV- ERABLE (UG/L AS CR) (01034)	COBALT, TOTAL RECOV- ERABLE (UG/L AS CO) (01037)	COPPER, TOTAL RECOV- ERABLE (UG/L AS CU) (01042)	IRON, TOTAL RECOV- ERABLE (UG/L AS FE) (01045)	IRON, DIS- SOLVED (UG/L AS FE) (01046)
SEP												
DATE	LEAD, TOTAL RECOV- ERABLE (UG/L AS PB) (01051)	MANGA- NESE, TOTAL RECOV- ERABLE (UG/L AS MN) (01055)	MANGA- NESE, DIS- SOLVED (UG/L AS MM) (01056)	MOLYB- DENUM, TOTAL RECOV- ERABLE (UG/L- AS MO) (01052)	<100 NICKEL, TOTAL RECOV- ERABLE (UG/L AS NI) (01067)	<10 SILVER, TOTAL RECOV- ERABLE (UG/L AS AG) (01077)	ZINC, TOTAL RECOV- ERABLE (UG/L AS ZN) (01092)	ALUM- INUM, TOTAL RECOV- ERABLE (UG/L AS AL) (01105)	LITHIUM TOTAL RECOV- ERABLE (UG/L AS LI) (01132)	SELE- NIUM, TOTAL (UG/L AS SE) (01147)	MERCURY TOTAL RECOV- ERABLE (UG/L AS HG) (71900)	20
SEP 26	<5	<10	<10	<1	2	<1	<10	<10	30	<1	0.2	
20	2	-10	-10		2	**	-10	-10	50		٠.5	

January 14, 1988

MEMORANDUM FOR THE RECORD

FROM:

Nobu Kaneshiro

SUBJECT: Trip to Molokai for Final Inspection of Job No. 35-9W-F

Drilling Kualapuu Mauka Exploratory Well

Persons Present:

Paul Wandke and Tui - Roscoe Moss Company George Harada, Tom Matayoshi, Mitchell Ohye and Nobu Kaneshiro -DOWALD

On Tuesday, January 12, 1988, Mitchell Ohye and I went to Molokai to conduct a final inspection for the subject well. As a requirement for this project the contractor ran a video log of the well from the surface to its total depth. The video log was successfully completed and the well was covered with a steel plate tack-welded to the top of the exposed casing. Hence, this well project was approved and accepted.

George Harada and I also inspected the Kualapuu Reservoir for potential erosion of embankment areas due to wave action. George indicated the water level is at about the 43-foot elevation and approximately 5 feet above the lined portion. The reservoir water was exceptionally calm with hardly any wave action. (See attached photos.)

Later, George, Tommy, Mitchell and I went through the Molokai tunnel to inspect the Waikolu Valley exploratory wells project. The contractor started to drill the first well (about 40 ft.) without much problem. The other two wells are upstream from the first well.

NK:ln Attach. JANUARY 19 1988 NEMORENDUM FOR THE RELOKD FROM: MITCHELL OHYE GUBJECT: KUALAPUL MAUKA WELL 0801-03 MOUNEAR TELENGION LOD

D THE CHOICH LOW WAS MADE OF THE KLALAPUL MALKA WELL ON JANUARY IP, 1988 BY THE ROSCOE MOSS CO., WEDTHER MAS CLEAR AND SELECT THRING LOUDING WERE PAUL MANKE AND I HELPER I FEGURE MOSS CO.), MITCHELL DIFFE AND TOMMY L. D.O. W. A. L.D.)

THE LANICHA LENS WAS REPERENCED TO BROWN GURFALE.
WILL SHAKTED LOUDING AT 0900 ARS. AND DESCRIPTION THE FOLLOWING:

- I) THE PLANK LASING IS IN MOOD CONDITION DOWN TO 1027 H. DEILLERS LOG SHOWS PEPH OF SLANK EASING AT 1027 H.
- P) Lamera LENS LIT WATER AT 1087 H., FICTURE VERY CLOUDY, HARD TO CRE, LLOUDINGED DUE TO ME FROM PUMPTESTING.
- 3) MOTION OF PERFORATED LAGING IS AT 1579 A. TON 1579 A. TON 1679 A. TON SACRED OF PERFORMED OF 1077 A.
- 4) POSTORA OF WELL IS 1133 H.
 LOW SHOWS 1136 H 3 H OF YOU MARKED.
- (1) END TELEVISION LOW ST. 1070 WES.

- MEED TAPE HEAD. OF W.L ON 1-21-87 IS 11.7 A SWL, MSL

Mychell one

October 6, 1987

MEMORANDUM FOR THE RECORD

FROM:

Mitchell K. Ohye

SUBJECT: Kualapuu-Mauka Well 0801-03, Molokai

A four-day pumping test was performed on the subject well from September 22-26, 1987. After it was deepened 36 ft. to a final depth of 1136 feet (-99 ft. msl). A sustained pumping rate of 1000 gallons per minute was established and the drawdown in the well ranged from 8.7 ft. to a stabilized 10.65 ft. The static water level measured 11.70 msl, on July 27, 1987 by steel tape. Chlorides were 66-70 ppm and temperature was 70.0°F.

The well was pumped for 96 continuous hours and recovered to within .5 ft. from the beginning static water level five minutes after shutdown.

On September 1, 1987, prior to deepening 36 feet from a depth of 1100 ft. (-63 ft., msl), the well was pumped for about 5 hours at a maximum rate of 517 gpm and drawdown of 21.15 ft. Therefore, the yield of the well was increased by the deepening.

MITCHELL K. OHYE

Morehul K. Oh

MKO: ko


STATE OF HAWAII DEPARTMENT OF LAND AND NATURAL RESOURCES DIVISION OF WATER AND LAND DEVELOPMENT

KUALAPUU MAUKA 0801-03

AS BUILT SECTION

Drilled: September 1987

Driller: Roscoe Moss Company



NOT TO SCALE

Job No.35-9W-F

. Kualapuu Mauka Well 0801-03, Molokai


(Ground Ele	evation -			ft.	msl	
•	Top of Ca	sing		· ₋	ft.	msl	
(Casing si	ze)_	14I.D	. inche	S
I	Blank Cas	ing Depth			<u>1027</u> ft.	(ft. msl)
:	Shutter S	creen Dep	th		1077 ft.	(ft. msl)
	Total Dep	th of Wel:	1		113 6 ft.	(ft. msl)
;	Static Wa	ter Level	(Elevation	_	ft.		ft. msl)
		Airline		·	1050 ft.		ft. msl)
		ucted by			Mitchell K.		20. 11027
•	rest Cond	accea by		-	MICCHEII K.	Onye	
Date		Pumping	Airline	Drawdown	Chlorides	Temp.	Remarks
& Time	Sample No.	Rate (GPM)	(FEET)	(FEET)	(PPM)	(F)	
September 0810 0815 0830	22, 1987	0 0 0 Sta	21.80 21.80 21.80 ert Pumping-	(Static) -Adjust to 3.00	500 gpm	M∈ 70	eter Readin 2033940 ¢
0845	1 2	536	18.90	2.90	66		
0900 0915		545 500	18.80 19.10	3.00 2.70	68	70	
0930 0945	3	517 500	19.00 19.10	2.80 2.70	70	70	
1000	4	492	19.15	2.65	70	70	
			Adjust	to 900 gp	m		
1005 1015 1030 1045 1100	5 6 7	930 900 900 893 900	14.60 14.80 14.70 14.75 14.50	6.20 6.00 6.10 6.05 6.30	70 70	70 70	

Date &	Sample	Pumping Rate	Airline	Drawdown	Chlorides	Temp.	Remarks
Time	No.	(GPM)	(FEET)	(FEET)	(PPM)	(F)	
September	22, 1987						
			Adjust Ra	ate to 900	gpm		
1115 1130	8	900 900	14.60 14.50	6.20 6.30	70	70	
1130	Ū	700		ate to 700		, -	
1135 1145 1230	9 10	724 707 707	16.80 16.90 16.90	5.00 4.90 4.90	70 70	70	
1300 1400 1430	11 12	700 700 700	16.95 16.95 17.00	4.85 4.85 4.80	70 70	70	
			Adjust	to 600 gpm	ı		
1435 1445 1500 1515 1530	13	631 642 642 631 631	17.65 17.55 17.55 17.70 17.75	4.15 4.25 4.25 4.10 4.05	70		
			Adjust	to 1000 gp	m		
1550 1600 1630 1700 1800	14 15 16	1000 1000 1000 1017 1017	13.10 13.00 12.90 12.80 12.65	8.70 8.80 8.90 9.00 9.15	68 69		
1900 2000 2100 2200 2300 2400	17 18 19 20 21 22	1017 1017 1017 1017 1017 1017	12.55 12.50 12.50 12.35 12.25 12.15	9.25 9.30 9.30 9.45 9.55 9.65	69 70 69 68 69 68	70	


Date &	Sample	Pumping Rate	Airline	Drawdown	Chlorides	Temp.	Remarks
Time	No.	(GPM)	(FEET)	(FEET)	(PPM)	(F)	
September	23, 1987						
0100	23	1017	12.05	9.75	70		
0200	24	1017	12.05	9.75	70 70		
0300	25	1017	12.00	9.80	69		
0400	26	1017	11.95	9.85	68		
0500	27	1017	11.90	9.90	68		
0600	28	1017	11.75	10.05	68		
0700	29	1017	11.70	10.10	65		
0800	30	1017	11.85	9.95	65		
0900	31	1017	11.75	10.05	68		
1000	32	1017	11.70	10.10	68		
1100	33	1017	11.70	10.10	00		
1200	34	1010	11.80	10.00	68		
1300	35	1010	11.80	10.00	00		
1400	36	1010	11.90	9.80	68		
1500	37	1017	11.70	10.10	00		
1600	38	1017	11.65	10.15	68		
1700	39	1017	11.55	10.25	• •		
1800	40	1017	11.55	10.25			
1900	41	1017	11.65	10.15			
2000	42	1017	11.55	10.25	68		
2100	43	1017	11.55	10.25			
2200	44	1017	11.65	10.15	68		
2300	45	1017	11.55	10.25			
2400	46	1017	11.55	10.25			
September	24 1097						
Pehremmer	24, 1907						
0100	47	1017	11.40	10.40	65		
0200	48	1017	11.25	10.55			
0300	49	1017	11.25	10.55	68		
0400	50	1017	11.25	10.55			
0500	51	1017	11.15	10.65	66		
0600	52	1017	11.15	10.65			
0700	53	1023	11.15	10.65		69.	5
0800	54	1027	11.15	10.65		, עס	
0900	55 5.6	1027	11.20	10.60	60		
1000	56	1017	11.30	10.50	68		
1100	57	1017	11.35	10.45	60		
1200	58	1017	11.35	10.45	68		

Date		Pumping	Airline	Drawdown	Chlorides	Temp.	Remarks
& Time	Sample No.	Rate (GPM)	(FEET)	(FEET)	(PPM)	(F)	
September	24, 1987						
1 200		1000	11 40	10.40			
1300 1400		1000 1000	11.40 11.45	10.40 10.35			
1500		1000	11.45	10.35			
1600	58	1000	11.65	10.15	68	70	
1700	20	1000	11.55	10.15	00	70	
1800	59	1000	11.55	10.25			
1900	3)	1000	11.65	10.15		70	
2000	60	1000	11.55	10.25	68	70	
2100	00	1000	11.65	10.25	00		
2200	61	1000	11.65	10.25		70	
2300	01	1000	11.65	10.15		, 0	
2400	62	1000	11.55	10.15	68		
2400	02	1000	11.55	10.25	00		
September	25, 1987						
0100		1000	11.60	10.20			
0200	63	1000	11.60	11.20			
0300	0.5	1000	11.60	10.20			
0400	64	1000	11.80	10.00	68		
0500	04	1000	11.85	9.95	00		
0600	65	1000	11.90	9.90			
0700	0.5	1000	12.00	9.80			
0800	66	1000	11.75	10.05	66		
0900	00	1000	11.65	10.15	• •		
1000	67	1017	11.45	10.35	70		
1100	0,	1017	11.45	10.35	, 0		
1200	68	1000	11.90	9.90	70		
1300	00	1007	11.60	10.20	. •		
1400	69	1007	11.50	10.30	68		
1500	• • •	1007	11.80	10.00			
1600	70	984	12.00	9.80			
1700	. •	984	11.65	10.15			
1800	71	1000	11.95	9.85	68		
1900	'	1000	12.00	9.80			
2000	72	1000					
2100		1000	12.20	9.60			
2200	73	1000	12.20	9.60	68		
2300		1000	12.20	9.60	- -		
2400	74	1000	11.75	10.05			

Date &	Sample	Pumping Rate	Airline	Drawdown	Chlorides	Temp.	Remarks
Time	No.	(GPM)	(feet)	(feet)	(ppm)	(F)	
eptember	26, 1987						
0100		1000	11.70	10.10			
0200	75	1000	11.70	10.10	68		
0300	7.0	1000	11.70	10.10			
0400	76	1000 1000	11.90 11.90	9.90 9.90			
0500 0600	77	1000	11.90	9.90			
0700	, ,	1000	11.90	9.90			
0800	78	1000	11.90	9.90	68		
			Stop Pum	ping- Recov	ery		
lapsed Ti	me						
minutes							
01		0	19.90	1.90		1	Meter Rdg.
03		0	21.25	.55			26009500
05		0	21.30	.50			100
07		0	21.30	.50	Gals. Pur	nped	5,670,100
09		0	21.25 21.25	.55 .55			
11 13		0 0	21.25	.55			
15		0	21.25	.55			
20		Õ	21.30	.50			
30		0	21.30	.50			
45		0	21.35	.45			
0900) 60		0	21.35	.45			
75 90		0 0	21.40	.40			
90		0	21.40	.30			
		1.3					
1000)120		0	21.55	. 25	•		




TIME IN MINUTES



T. 11=

XA. 1.141 5



October 5, 1987

Mr. Vince G. Bagoyo, Jr. Director
Department of Water Supply County of Maui
P.O. Box 1109
Wailuku, Maui 96793-0343

Dear Mr. Bagoyo:

Results of Drilling and Testing of Kualapuu-Mauka Exploratory Well 0801-03, Central Molokai

The Division of Water and Land Development has completed the drilling and testing of a 1,136-foot deep exploratory well at Kualapuu-Bauka, Central Molokai, with good results.

A four-day pumping test conducted on September 22-26, 1987, indicates that the well is capable of producing 1.4 million gallons per day of fresh potable water having a chloride content of only 70 milligrams per liter (U.S. Public Health Service arbitrary limit for potable water is 250 parts per million). The well was pumped for 96 hours at a rate of 1,000 gallons per minute (1.4 mgd) with a stabilized well drawdown (10.0 ft.) and chloride content. Recovery of the drawdown was nearly instantaneous after pumping was ended, and the temperature of the water measured 70.0°F.


Other pertinent facts about the well include: (1) ground elevation, 1037 feet above mean sea level; (2) static water level, 11.7 ft. above mean sea level; (3) casing size, 14-inch diameter; and (4) casing depth, 1,136 ft.

The favorable test outcome now allows your office to proceed with the next phase of the project—to get the well into production. If you have any questions, please call me at 548-7533.

Sincerely,

MANABU TAGOMORI Manager-Chief Engineer

DL:dh



September 3, 1987

MEMORANDUM FOR THE RECORD

FROM:

Mitchell Ohye

SUBJECT:

Kualapuu Well 0801-03, Molokai Pumping Test

On September 1, 1987, Suzie and I traveled to the Kualapuu Mauka Well to perform a pumping test. During development of the well by pump surging, the diesel engine fan and right angle gear drive broke. According to the driller the equipment will have to be shipped to Honolulu for repairs.

The following data was collected before the breakdown:

Pumping Rate	Drawdown (ft.)
414 gpm	10.6
453	12.05'
517	21.15'

Initial chlorides were 105 ppm decreasing to 90 ppm, after pump surging for 3 to 4 hours.

	Recovery	Data
--	----------	------


Time (after shutdown)	Drawdown
1 minute	8.55 ft.
2	.95
3	+2.05
5	Above range of manometer
10	Static

Called in results to Dan Lum-he recommended that the pump be pulled and well deepened 30 to 40 ft.

Mitchell 6/1

MITCHELL OHYE

Me Ling Buld he me Lines of this men.



GALLONS PER MINUTE X 100

September 3, 1987

MEMORANDUM FOR THE RECORD

FROM:

Mitchell Ohye

SUBJECT: Kualapuu Well 0801-03, Molokai Pumping Test

On September 1, 1987, Suzie and I traveled to the Kualapuu Mauka Well to perform a pumping test. During development of the well by pump surging, the diesel engine fan and right angle gear drive broke. According to the driller the equipment will have to be shipped to Honolulu for repairs.

The following data was collected before the breakdown:

Pumping Rate	Drawdown (ft.)	1. 36 (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16) (1. 16)
414 gpm	10.6'	·
453	12.05'	
517	21.15'	

Initial chlorides were 105 ppm decreasing to 90 ppm, after pump surging for 3 to 4 hours.

Recovery Data

Time (after shutdown)	Drawdown
1 minute	8.55 ft.
2	.95
3	+2.05
5	Above range of manometer
10	Static

Called in results to Dan Lum-he recommended that the pump be pulled and well deepened 30 to 40 ft.

Mitchiel Ch

MITCHELL OHYE

July 28, 1987

MEMORANDUM FOR THE RECORD

FROM:

•

Mitchell K. Ohye

SUBJECT:

Kualapuu Mauka Exploratory Well 0801-03, Molokai

Job No. 35-MW-F, Water Level Measurement

On July 27, 1987, I visited the subject well to accurately measure the water level. The reference point used was top of the 14-inch steel casing which stands 2.15 ft. above ground level. A temporary B.M. was transferred onto the drill rig and that point stands 1.7 ft. above ground level. Therefore, 2.15 ft. (height of 14-inch casing) minus 1.70 ft. (height of B.M.) equals .45 ft. difference plus 1039-ft. elevation of B.M.) equals 1039.45 ft. top of the 14-inch casing elevation (see attached).

A total of 1029 ft. of steel tape was lowered into the well, and a wet mark of 1.25 ft. recorded 1029 - 1.25 = 1027.75 ft.-depth to water from top of the 14-inch casing. 1039.45 ft.-top of casing elevation minus 1027.75 ft.-depth to water equals a water level of 11.70 ft. above msl at 10:30 a.m.

MITCHELL K. OHYE

Matchel K. Oh

MKO:ko Attach.